

WATER SERVICE RECORD

Name Benjamin Franklih Homes

Service No. 12

Address 7 Rumford Road

Location Lot 10 A

~~Repair~~ ~~Water~~ New Service

Comm 7-6-59

Date	Material	Amount	Total	Date	Amount
6-8-59	Labor	1 85		3-30-59	Deposit 10 00
6-9-59	"	1 85		7-6-59	* Returned 29 89
		3 70			47 11
	10% O. H.	37	4 07		NON CHARGE
55'	3/4" Copper Tubing @.3666	20 16	10.9.57	Labor	4 88
1	3/4" C x 1/2 IWH Stop & Waste	5 88	10'	3/4" Copper tubing	3 75
	17 x 3 Patch	17 00	1	3/4" C Corp Cock	4 64
		47 11	1	3/4" C Curb Cock	5 94
				1 Box & Rod	4 62
				1 Hour Trucking @ .75	75
				6-8-59	Labor 12.49
				6-9-59	" 13.49
				14'	3/4" Copper Tube @.3666 5. 13
				1	3/4" C Corp Cock 4 67
				1	3/4" C Curb Cock 6 07
				1	Box & Rod 5 00
				1	1/2 Straight Tailpiece 50
				1	1/2 Offset Tailpiece 50
5-26-83	Repaired tank by curb			1	Hr. Town Shovel @6.50 6 50
					78 93

* Applied to WWSR (25-38)

