

WATER SERVICE RECORD

Name Benj. Franklin Homes

Service No. 207

Address 8 Rumford Road

Location Lot 318

Repair—Renewal—New Service

Comm 12-15-58

Date	Material	Amount	Total	Date	Material	Amount
10/18/58	labor	3 62		10-6-58	Deposit	35 00
	10% overhead	36		1-6-59	Paid	16 32
			3 98		NON CHARGE	51 32
	104' 3/4" copper tubing @	.37 38	48	10/8/57	Labor	4 19
	1 3/4" Cx 1/2 IWH stop & waste	5 84		23' - 3/4"	Copper tubing	8 63
	1 3/4" C3 part union		2 27	1 3/4"	C Corp Cock	4 64
	1 hr. trucking @ .75		75	1 3/4"	C Curb Cock	5 94
			51 32	1	Box & Rod	4 62
				1 Hr.	Trucking @ .75	75
						28 77
					1 1/2 straight tail pc.	50
					1 1/2 offset tail pc.	50
						29 77
					Bill sent 1-5-58	16.32

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS
WATER DIVISION

Sketch of Service Here

A large rectangular grid of graph paper, consisting of 20 columns and 20 rows of small squares, intended for sketching service details.

Connection made in Street. Work completed

Remarks:
.....
.....