

WATER SERVICE RECORD

1185

Name Blake Ogden

Service No. 359

Address 37 Sherburne Road

Location

Repair - ~~Renewal~~ - New Service

Com. 11-30-53

Date	Material	Amount	Total	Date	Amount
11/13/53	Labor	6 50		11-3-53	20 00
	10% Overhead	65	7 15	11-30-53	1 86
	42' - 3/4" Copper tubing @ .3629	15 24			58 14
	1 - 3/4" C x 1/2" I.W.H. stop & waste	4 00			
	2 hrs. Littlefield shovel @ 7.50	15 00		11/3/53	Labor
	1 hr. trucking		75		6 50
	patching 16 x 3		16 00		20' - 3/4" Copper tubing @ .3629
			58 14		7 26
					1 - 3/4" C. corp-cock
					4 33
					1 - 3/4" C x 3/4" C. curb-cock
					4 67
					1 box and rod
					3 90
					1 - 1/2" offset tail piece
					50
					1 - 1/2" straight tail piece
					50
					2 hrs. Littlefield shovel @ 7.50
					15 00
					1 hr. trucking
					75
					43 41

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large grid of graph paper, approximately 20 columns wide and 25 rows high, intended for sketching service details.

Connection made in Street. Work completed

Remarks:

.....

.....