

Name Minnie H. Ricker

Service No. #2369  
2502

Address ~~138 Traincroft Rd., Medford~~

105 Simonds Rd. Location <sup>105</sup> ~~99~~ Simonds Road, (Lots 25, 26, 27)

Kind of Pipe

Size

Size of Main

~~Repair - Renewal -~~ New Service

Location

Date	Material	Amount	Total	Date	Amount
8/21/34	45' 1" C. Pipe @ .20	\$9 00			
9-25-34 Russell - 1934	1 S & W Trucking	2 75			
		75	\$12 50		
	4 Hrs. Labor @ .55	2 20			
	3 " " @ .60	1 80	4 00		
	10% Overhead		40		
	<b>COST</b>		\$16 90		
	<b>CHARGE</b>				
	Estimated cost,	\$19 35	\$19 35		
	45' @ .45 figures \$20.25, but as deposit <del>labor</del> exceeded actual cost, let it go for the estimated price.				
3/3/83	3' 1" Copper tubing - REPAIR W.O. #409				
	2 1" Style 88				

Aug. 25 1934 - Deposit 19 35

Hadley Bros., Inc., Lexington

