

Name William Place

8722

Service No. 211

Address 8 Tower Road

Lexington, Mass.

Location 8 Tower Road

Kind of Pipe

Size

Size of Main

~~Repair~~—Renewal—New Service

Location

Date

Material

Amount

Total

Date

Amount

| | | | |
|---------------|--------------------------------|------|-------|
| Sept. 25, '48 | Labor | 1 25 | 1 25 |
| | 10% Overhead | | 13 |
| | 39' - 3/4" Copper Tubing @.255 | 9 95 | 9 95 |
| | 1 - 3/4" C x 1/2" I.W.H. S & W | 3 15 | 3 15 |
| | Trucking 1 hr. @.75 | 75 | 75 |
| | | | <hr/> |
| | | | 15 23 |

Com. 10/25/48

| | | |
|---------------|--------------------------------|-------|
| Sept. 20 '48 | Deposited | 25 00 |
| Oct. 27 '48 | Returned | 9 75 |
| | Non-Charge | <hr/> |
| | | 15 23 |
| Sept. 25, '48 | Labor | 1 25 |
| | 25' - 3/4" Copper Tubing @.255 | 6 38 |
| | 1 - 3/4" C Corp-cock | 3 00 |
| | 1 - 3/4" C x 3/4" C Curb-cock | 3 68 |
| | 1 - Box & Rod | 3 55 |
| | 1 - 1/2" Offset Tail Piece | 30 |
| | 1 - 1/2" Straight Tail Piece | 30 |
| | Trucking 1 hr. @.75 | 75 |
| | | <hr/> |
| | | 19 21 |

Labor

