

## WATER SERVICE RECORD

Name Sterling Builders

Service No. 111

Address 41 Turning Mill Road

#7177

Location Los 24

Report ~~RENEWAL~~ - New Service

Comm 12-1-58

Date	Material	Amount	Total	Date	Amount
6/33/58	labor	7 60		6-16-58	75 00
	10% overhead	76		12-1-58	74
			8 36		75 74
	150' 3/4" copper tubing @ .37		55 50		
	1 3/4" Cx 1/2" IWH stop & waste		5 84		Service installed by
	2 3/4" 3 part Unions @ 2.27		4 54		developer July, 1957
	2 hrs. trucking @ .75		1 50	1 1/2	straight tail piece
			75 74	1 1/2	offset tail piece
					1 00

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**

**WATER DIVISION**

Sketch of Service Here

A large grid of graph paper, approximately 20 columns wide and 20 rows high, intended for sketching service details.

Connection made in ..... Street.                      Work completed .....

Remarks: .....  
.....  
.....