

WATER SERVICE RECORD

Name

Service No.

Address

11 Wingate Road

Location

~~REPAIR - REPAIR~~ - New Service

Service to curb only

Date	Material	Amount	Total	Date	Amount
12-8-56					
	58' 3/4" Copper				
	1 3/4" C. X 1/2" I.W.H. Stop & Waste				
					Non Charge
				9/16/55	Labor 1 60
					9'-3/4" Copper tubing @.56 5 04
					1-3/4" C Corp Cock 4 33
					1-3/4" C Curb Cock 4 67
					1 Box & Rod 3 90
					1 hr. trucking @.75 75
					<u>20 29</u>

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

WATER DIVISION

Sketch of Service Here

A large rectangular grid of graph paper, consisting of approximately 20 columns and 25 rows of small squares, intended for sketching service details.

Connection made in Street. Work completed

Remarks:

.....

.....