

# WATER SERVICE RECORD

Name Iovino

Service No. 128

Address Winter Street Pit (#150 )

Location

~~Repair & Renewal~~ - New Service

Com. 12-31-50

Date	Material	Amount	Total	Date	Description	Amount	
June 28, '50	Labor	15 05	15 05	June 28, '50	<i>Deported</i>	50 00	
	10% Overhead		1 51				
	500 Sewer Brick		17 30			No Charge	37 61
	Town Shovel 1 hr. @ 3.00		3 00	June 28, '50		Labor	46 00
	Trucking 1 hr. @ .75		75		180' - 1" Copper Tubing @ .284	51 12	
			37 61		6 - 2" C. L. Pipe @ .73	4 38	
					4 - 1" C Corp-cocks	18 48	
					1 - 1" C x 2" I 4-way Branch	12 18	
					1 - 2" T.H. Gate Valve	10 06	
					1 - Box & Rod	3 35	
					1 Pit Cover & Frame	14 00	
					Town Shovel 3 hrs. @ 3.00	9 00	
					Allis-Chalmers 1 hr. @ 3.00	3 00	
					Trucking 2 hrs. @ .75	1 50	
						173 07	

DATE \_\_\_\_\_

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

**WATER DIVISION**

Sketch of Service Here

A large grid of graph paper for sketching service locations, consisting of 15 columns and 20 rows of small squares.

Connection made in ..... Street.                  Work completed .....

Remarks: .....

.....

.....